

Lead Service Line Inve	ntory Temi	olate
------------------------	------------	-------

*Please enter information in the empty box next to each section	Water System N	ame	Steger	System ID Number:	IL0314860	Current Invento	ory Date:	4/9/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	2614 Total Lead	831 Total Non-Lead	1780 Total Galvanize replacer	' 9	Total Unknown:	0	Website link to Material Inventory:	gettheleadoutil.com/steger

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:		
							Copper - No Lead	Copper - No Lead Solder (C	Copper - No Lead Solder (C)	Lead (L)							
		Group Homes, Parks, Playgrounds,					Solder (C) Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Conner - Lead Solder	Galvanized Requiring Replacemnt (GRR)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y).				Copper - No Lead Solder (C)		IF customer refused
	Sample site number is the 7 digit number	Special Care Facilities, Hospitals,					Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	If the galvanized service line material was never	Enter date		If previous column was	Galvanized (G)		access to property, date waiver obtained
	starting with "LP" or				What year was the	How was the Material of this Service Line					downstream of any Lead	customer was notified of Lead		marked (Y), provide date the Lead Service Line was			by PWS or date PWS
	" LA". / If address is not a	Facilities	Yes (Y) or No (N)	PWS-Owned service line installed, if known?	customer side service line installed, if known?	Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc	Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	section, mark No (N). / If Yes, that section of service line	Service Line. /	Yes (Y) or No (N)	replaced. /	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	notified IDPH of refusal to sign waiver. /
	lead and copper					., ., ., .,	Cast/Ductile Iron or	Lead (L)	Lead (L)		should be marked as Galvanized Requiring	If Service Line is not Lead put N/R		Leave blank if previous column was (N).	Cast/Ductile Iron or Transite		Leave blank if
	sample site mark "N/A"						Transite (O) Plastic - PVC, HDPE,	Cast/Ductile Iron or	Cast/Ductile Iron or		Replacement in the	zeda par ny n			(0)		customer has not refused access.
	IN/A						PEX (P)	Transite (O)	Transite (O) Plastic - PVC, HDPE,		appropriate immediately preceding column(s).						reruseu access.
		Yes (Y) or No (N)					Unknown (U)	Plastic - PVC, HDPE, PEX (P)	PEX (P)		preceding column(s).				Leave blank if no Lead		
							Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)						Service Line was replaced.		
								Unknown Not Lead (UNL)	Unknown Not Lead (UNL)								
12 W 30TH STREET		N	Υ	1948	1948	Statistical Model	U	L	L	L	N	5/15/2024	N				
78 W 37TH STREET		N	Υ	1904	1904	Visual Confirmation	U	L	L	L	N	5/15/2024	Υ	3/24/2025	С	N	
3418 HALSTED BLVD		_N	N	1924	1924	Indoor Inspection - Contractor	U	L	L	L	N	5/15/2024	Υ	3/25/2025	С	N	
3423 HALSTED BLVD		_ N	Υ	1929	1929	Indoor Inspection - Contractor	U	L	L	L	N	5/15/2024	Υ	3/28/2025	С	N	
3508 HALSTED BLVD		N	N	1909	1909	Excavation - Contractor	U	L	L	L	N	5/15/2024	Υ	3/26/2025	С	N	
3509 HALSTED BLVD		N	Y	1949	1949	Notified by Customer	U	L	С	L	N	5/15/2024	Υ	3/28/2025	С	N	
3514 HALSTED BLVD		N	N	1905	1905	Visual Confirmation	U	L	L	L	N	5/15/2024	Υ	3/27/2025	С	N	
3534 HALSTED BLVD		_N	N	1914	1914	Excavation - Contractor	U	L	С	L	N	5/15/2024	Υ	3/31/2025	С	N	
3540 HALSTED BLVD		N	Y	1929		Indoor Inspection - Contractor	U	L	L	L		-,,	Υ	3/25/2025		N	
3600 HALSTED BLVD		N .	Y	1900		Existing Records	U	L	L	L		5/15/2024	Υ	3/26/2025		N	
3610 HALSTED BLVD		N	Y	1929		Visual Confirmation	U	L	С	L		5/15/2024	Υ	3/31/2025		N	
3624 HALSTED BLVD		-	N	1923		Indoor Inspection - Contractor	U	L	L	L		3/13/2021	Y	3/27/2025		N	
3642 HALSTED BLVD		N	Y	1935		Existing Records	U	L	L	L		5/15/2024	Y	3/31/2025		N	
3700 STELLA BLVD		_N	Y	1924		Indoor Inspection - Contractor	U	L	L			5/15/2024	Y	3/27/2025		N	
3706 STELLA BLVD			N	1910		Indoor Inspection - Contractor	U	L	L	=		5/15/2024	Y	4/1/2025		N	
3714 STELLA BLVD			N	1905		Excavation - Contractor	U	L	С	L		5/15/2024	Y	4/1/2025		N	
3723 STELLA BLVD			N	1914		Excavation - Contractor		L	L .	L		5/15/2024	Y	4/1/2025		N	
3727 STELLA BLVD			N	1887		Indoor Inspection - Contractor	U	L	L	L		5/15/2024	Y	4/1/2025		N	
3730 STELLA BLVD		.,	Y	1914		Excavation - Contractor	U	L	L	L		5/15/2024	T V	4/3/2025		IN .	
3733 STELLA BLVD			N N	1894 1939		Indoor Inspection - Contractor Indoor Inspection - Contractor	U	1	L			5/15/2024	v	4/4/2025 4/7/2025		N N	
3735 STELLA BLVD 3736 STELLA BLVD		N	v	1939		Existing Records	II	1	1			5/15/2024 5/15/2024	v	4/7/2025		N	
3739 STELLA BLVD		N N	N N	1899		Indoor Inspection - Contractor	U	L				5/15/2024	v	4/1/2025		N.	
3744 STELLA BLVD			Υ Υ	1904		Indoor Inspection - Contractor			L			5/15/2024	v	4/4/2025		N.	
3747 STELLA BLVD		-	N N	1904		Indoor Inspection - Contractor	U		1	i.			<u>т</u> У	4/8/2025		N	
3750 STELLA BLVD			N	1900		Excavation - Contractor	U	L	L	L		5/15/2024	Υ	4/4/2025		N.	
3751 STELLA BLVD			N	1929		Indoor Inspection - Contractor	U	L		ī.			Y	4/3/2025		N	
3752 STELLA BLVD			N	1927		Excavation - Contractor	-	-	L			5/15/2024	Y	4/4/2025		N	
3755 STELLA BLVD			Y	1927		Indoor Inspection - Contractor	-	L	L	L			Y	4/3/2025		N	
3756 STELLA BLVD			N N	1909		Indoor Inspection - Contractor	U	-	L	L		5/15/2024	Y	4/9/2025		N	
3763 STELLA BLVD			Y	1904		Indoor Inspection - Contractor	-	L	L				<u>,</u> У	4/7/2025		N	
3767 STELLA BLVD			Y	1904		Indoor Inspection - Contractor	U		L			5/15/2024	v	4/7/2025			

3771 STELLA BLVD 3411 GREEN STREET 3415 GREEN STREET 3418 GREEN STREET 3422 GREEN STREET 3430 GREEN STREET	Sample site number. N N N	acility or Area? s	Identified Since Last Submitted Inventory	Line was Installed	Side Service Line was Installed	Identification	Pigtail	Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Dawleson		refused access to the	
3411 GREEN STREET 3415 GREEN STREET 3418 GREEN STREET 3422 GREEN STREET 3430 GREEN STREET	N N	<u>Y</u>	N						Material	Line	downstream of Lead?	Service Line	this Location?	Replaced	Replacement	property?	customer refused access to property
3415 GREEN STREET 3418 GREEN STREET 3422 GREEN STREET 3430 GREEN STREET		·		1946	1946	Excavation - Contractor		L	L I		N	5/15/2024	Y	4/8/2025	c r	N	
3418 GREEN STREET 3422 GREEN STREET 3430 GREEN STREET			1	1924	1924	Statistical Model	U	L	C		N	5/15/2024	Y	3/21/2025	C I	N	
3422 GREEN STREET 3430 GREEN STREET	N	Y	(1924	1924	Notified by Customer	U	L	L I		N	5/15/2024	Υ	3/21/2025	C I	V	
3430 GREEN STREET		N	V	1925	1925	Indoor Inspection - Contractor	U	L	L I		N	5/15/2024	Υ	3/21/2025	c r	N	
	N	N	N	1900	1900	Excavation - Utility	U	L	L I		N	5/15/2024	Υ	3/21/2025	C I	N	
	N	<u>Y</u>	<u> </u>	1900	1900	Notified by Customer	U	L	C I		N	5/15/2024	Υ	3/20/2025	c r	N	1
3501 GREEN STREET	N	N	N	1945	1945	Excavation - Contractor	U	L	C I	. 1	N	5/15/2024	Y	3/20/2025	C I	N	
3505 GREEN STREET	N	<u>N</u>	N .	1947		Excavation - Utility	U	L	L I			5/15/2024	Υ	3/17/2025	c I	N	
3508 GREEN STREET	N			1934			U	L	L I			-,, :	Y	3/20/2025	C I	N	
3534 GREEN STREET	N	<u>N</u>		1935		Excavation - Contractor	U	L	L I			5/15/2024	Υ	3/18/2025	C I	N	
3535 GREEN STREET	N	<u>N</u>	N .	1899		Excavation - Utility	<u>u</u>	L	C .			-,,	Υ	3/19/2025	C I		
3539 GREEN STREET	N	_	/	1904		Indoor Inspection - Contractor	IJ	L				3/ 13/ 202 :	Y Y	3/19/2025	C r		
3609 GREEN STREET 3615 GREEN STREET	N	<u> -</u>	<u> </u>	1909 1944			IJ			•		-,,	<u>Y</u> Y	3/19/2025 3/13/2025	C 1	N .	
3636 GREEN STREET		- 1 Y	/	1950		-	<u>. </u>	1					Y	3/24/2025	C 1	v u	
3647 GREEN STREET		÷		1929		-	J	1					<u>,</u> У	3/24/2025	C .	v v	
3416 PEORIA STREET			N	1949		-	U	1					y	3/7/2025	C I	V	
3420 PEORIA STREET	N N		·	1900		Indoor Inspection - Contractor	U	L	L I			5/15/2024	Y	3/10/2025	c i	N	
3425 PEORIA STREET	N		N	1900		Excavation - Utility	U	L	L I			5/15/2024	Y	3/11/2025	c r	N	
3432 PEORIA STREET	N	N	N	1924		Excavation - Contractor	U	L	L I			5/15/2024	Y	3/11/2025	c r	N	
3438 PEORIA STREET	N	N	N	1941	1941	Excavation - Contractor	U	L	С		N	5/15/2024	Y	3/11/2025	C I	N	
3507 PEORIA STREET	N	N	N	1959	1959	Excavation - Utility	U	L	C I		N	5/15/2024	Y	3/12/2025	C I	N	
3511 PEORIA STREET	N	N	V	1959	1959	Excavation - Utility	U	L	C I		N	5/15/2024	Υ	3/11/2025	c r	N	
3526 PEORIA STREET	N	<u>Y</u>	(1924	1924	Existing Records	U	L	L I		N	5/15/2024	Υ	3/12/2025	C I	N	
3531 PEORIA STREET	N	Y	(1948	1948	Existing Records	U	L	L I		N	5/15/2024	Υ	3/13/2025	C I	N	
3534 PEORIA STREET	N	N	N .	1944	1944	Excavation - Contractor	U	L	C I		N	5/15/2024	Υ	3/12/2025	c r	N	
3535 PEORIA STREET	N	<u>Y</u>	<u>(</u>	1947	1947	Existing Records	U	L	L I	-	N	5/15/2024	Υ	3/12/2025	C I	N	
3544 PEORIA STREET	N	N	N	1909		Excavation - Contractor	U	L	L I			-,, :	Y	3/13/2025	C r	N	
3601 PEORIA STREET	N	-		1947		Excavation - Contractor	U	L	C			5/15/2024	Y	3/13/2025	C I	N .	
3608 PEORIA STREET	N	<u>Y</u>	·	1899			U	L	L I	-		-,,	Υ	3/13/2025	C r		
3626 PEORIA STREET	N	-		1945			U	L				-,,	Υ	3/17/2025	C I		
3633 PEORIA STREET 3424 SANGAMON STREET	N	<u>N</u>		1948			U U	L				-,,	Y Y	3/18/2025 3/6/2025	C r	N	
3432 SANGAMON STREET	N			1945 1904		Excavation - Contractor Indoor Inspection - Contractor	U.	ı				5/15/2024 5/15/2024	v	2/28/2025	C 1	N .	
3435 SANGAMON STREET	N		·	1942		Excavation - Contractor		1				5/15/2024	y	3/6/2025	C I	V	
3439 SANGAMON STREET	N N	N		1946		Existing Records	IJ	L				5/15/2024	<u>,</u> У	3/5/2025	C I	v N	
3443 SANGAMON STREET	N		N .	1947		-	U	L	C				Y	3/7/2025	c i	N	
3451 SANGAMON STREET	N	N	N	1918			U	L	L I			5/15/2024	Y	3/5/2025	c r	N	
3501 SANGAMON STREET	N	N	N	1939		·	U	L	L I				Y	3/5/2025	c r	N	
3505 SANGAMON STREET	N	N	N	1927	1927	Excavation - Contractor	U	L	C		N	5/15/2024	Y	3/3/2025	C I	N	
3509 SANGAMON STREET	N	N	N	1929	1929	Excavation - Contractor	U	L	L I		N	5/15/2024	Υ	2/27/2025	С	N	
3516 SANGAMON STREET	N	N	N	1929	1929	Visual Confirmation	U	L	C I		N	5/15/2024	Υ	2/28/2025	c i	N	
3529 SANGAMON STREET	N	N	N	1953	1953	Excavation - Contractor	U	L	C		N	5/15/2024	Υ	2/28/2025	C I	N	
3604 SANGAMON STREET	N	N	N	1927	1927	Existing Records	U	L	L I		N	5/15/2024	Υ	2/26/2025	c	N	
3608 SANGAMON STREET	N	N	N	1942		Existing Records	U	L	L			5/15/2024	Υ	2/26/2025	c i	N	
3621 SANGAMON STREET	N	N	N	1949		-	U	L	L				Y	2/26/2025	C I	N	
3625 SANGAMON STREET	N	_		1949		-	U		C				Y	2/25/2025	C	N	
3629 SANGAMON STREET	N	_		1919			U 	L	C			., ., .	Υ	2/26/2025	C	N	
3630 SANGAMON STREET	N			1939		Existing Records	U	L	L 1			5/15/2024	Y	2/26/2025	C I	N .	
3634 SANGAMON STREET	N	<u>N</u>		1946		-	U	L		•			Υ	2/25/2025		N	
3639 SANGAMON STREET	N	-		1929		-	U U	L	C	•			Y V	2/27/2025 2/7/2025		N.	
3506 MORGAN STREET 3514 MORGAN STREET	N N	_		1961 1924		Excavation - Contractor Excavation - Contractor	U .	ı				5/15/2024 5/15/2024	Y V	2/7/2025		N N	
3514 MORGAN STREET 3515 MORGAN STREET	N N			1924		-	U						<u>т</u> У	2/4/2025	<u> </u>	N	
3517 MORGAN STREET	N			1924			IJ	L	C I			5/15/2024	Y	2/4/2025	C	N	
3520 MORGAN STREET	N			1924		_	U	L					<u>'</u> Y	2/4/2025	C I	V	
3526 MORGAN STREET	N			1924			U	L	C I			5/15/2024	Y	2/5/2025	c	N	
3527 MORGAN STREET	N	N	N	1945		-	U	L	L				Y	2/5/2025	C	N	
3530 MORGAN STREET	N	N	N	1924			U	L	C I				Y	2/7/2025	C I	N	
3536 MORGAN STREET	N	N	N	1925			U	С	C I	NL		N/R	Y	2/10/2025	С	N	

Service Address	Lead and Copper Sample site number.	is this a nigh-rise	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?		Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
3548 MORGAN STREET		N	N	1909	1000	Excavation - Contractor	U	1	C		N	5/15/2024	v	2/11/2025	c	N.	
3601 MORGAN STREET		N	N	1929			U		L	l.	N		Y	2/11/2025		N	
3605 MORGAN STREET		N	N	1939		the state of the s	U	ī.	C	L	N		<u>Y</u>	2/10/2025		N	
3609 MORGAN STREET		 N	N	1942			U	L	С	L	N		<u>Y</u>	2/11/2025		N	
3625 MORGAN STREET		N	N	1949		·	U	L	С	L	N	5/15/2024	Υ	2/11/2025		N	
3628 MORGAN STREET		N	N	2008	2008	Excavation - Contractor	U	L	С	L	N	5/15/2024	Y	2/25/2025	С	N	
3627 MORGAN STREET		N	N	1939	1939	Excavation - Contractor	U	L	С	L	N	5/15/2024	Υ	2/11/2025	С	N	
3637 MORGAN STREET		N	N	1944	1944	Excavation - Contractor	U	L	С	L	N	5/15/2024	Υ	2/11/2025	С	N	
		_															
			_														
						·											
		_															
		_															
	_																
		_		•													

				V PMC												
Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Owned Service	Year Customer Side Service Line	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.		Submitted Inventory	Installed	was Installed				Material	Line	downstream of Lead?	Service Line	this Location?	 	property?	to property
				_												
				_												
				_												
				_												
				_												
_																

				V PMC												
Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Owned Service	Year Customer Side Service Line	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.		Submitted Inventory	Installed	was Installed				Material	Line	downstream of Lead?	Service Line	this Location?	 	property?	to property
				_												
				_												
				_												
				_												
				_												
_																

				V PMC												
Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Owned Service	Year Customer Side Service Line	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.		Submitted Inventory	Installed	was Installed				Material	Line	downstream of Lead?	Service Line	this Location?	 	property?	to property
				_												
				_												
				_												
				_												
				_												
_																

				V PMC												
Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Owned Service	Year Customer Side Service Line	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.		Submitted Inventory	Installed	was Installed				Material	Line	downstream of Lead?	Service Line	this Location?	 	property?	to property
				_												
				_												
				_												
				_												
				_												
_																

				V PMC												
Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Owned Service	Year Customer Side Service Line	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.		Submitted Inventory	Installed	was Installed				Material	Line	downstream of Lead?	Service Line	this Location?	 	property?	to property
				_												
				_												
				_												
				_												
				_												
_																

				V PMC												
Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Owned Service	Year Customer Side Service Line	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.		Submitted Inventory	Installed	was Installed				Material	Line	downstream of Lead?	Service Line	this Location?	 	property?	to property
				_												
				_												
				_												
				_												
				_												
_																

				V PMC												
Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Owned Service	Year Customer Side Service Line	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.		Submitted Inventory	Installed	was Installed				Material	Line	downstream of Lead?	Service Line	this Location?	 	property?	to property
				_												
				_												
				_												
				_												
				_												
_																

				V PMC												
Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Owned Service	Year Customer Side Service Line	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.		Submitted Inventory	Installed	was Installed				Material	Line	downstream of Lead?	Service Line	this Location?	 	property?	to property
				_												
				_												
				_												
				_												
				_												
_																

				V PMC												
Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Owned Service	Year Customer Side Service Line	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.		Submitted Inventory	Installed	was Installed				Material	Line	downstream of Lead?	Service Line	this Location?	 	property?	to property
				_												
				_												
				_												
				_												
				_												
_																

				V PMC												
Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Owned Service	Year Customer Side Service Line	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.		Submitted Inventory	Installed	was Installed				Material	Line	downstream of Lead?	Service Line	this Location?	 	property?	to property
				_												
				_												
				_												
				_												
				_												
_																

				V PMC												
Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Owned Service	Year Customer Side Service Line	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.		Submitted Inventory	Installed	was Installed				Material	Line	downstream of Lead?	Service Line	this Location?	 	property?	to property
				_												
				_												
				_												
				_												
				_												
_																

				V PMC												
Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Owned Service	Year Customer Side Service Line	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.		Submitted Inventory	Installed	was Installed				Material	Line	downstream of Lead?	Service Line	this Location?	 	property?	to property
				_												
				_												
				_												
				_												
				_												
_																

				V PMC												
Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Owned Service	Year Customer Side Service Line	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.		Submitted Inventory	Installed	was Installed				Material	Line	downstream of Lead?	Service Line	this Location?	 	property?	to property
				_												
				_												
				_												
				_												
				_												
_																

				V PMC												
Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Owned Service	Year Customer Side Service Line	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.		Submitted Inventory	Installed	was Installed				Material	Line	downstream of Lead?	Service Line	this Location?	 	property?	to property
				_												
				_												
				_												
				_												
				_												
_																

				V PMC												
Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Owned Service	Year Customer Side Service Line	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.		Submitted Inventory	Installed	was Installed				Material	Line	downstream of Lead?	Service Line	this Location?	 	property?	to property
				_												
				_												
				_												
				_												
				_												
_																

				V PMC												
Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Owned Service	Year Customer Side Service Line	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.		Submitted Inventory	Installed	was Installed				Material	Line	downstream of Lead?	Service Line	this Location?	 	property?	to property
				_												
				_												
				_												
				_												
				_												
_																

				V PMC												
Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Owned Service	Year Customer Side Service Line	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Service Line	Entire Serivice	Line Material ever	Notified of Lead	Previously Replaced at	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.		Submitted Inventory	Installed	was Installed				Material	Line	downstream of Lead?	Service Line	this Location?	 	property?	to property
				_												
				_												
				_												
				_												
				_												
_																

Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last	Year PWS- Owned Service	Year Customer Side Service Line	Source of Information Used for Service L	ne Gooseneck/	PWS-Owned Service	Customer Side Service Line	Classification for Entire Serivice	Was Galvanized Service Line Material ever		Was a Lead Service Line Previously Replaced at	Date Lead Service Line	Material of Service Line	Has the customer refused access to the	Date of customer waiver or IDPH notification, if
Service Address	number.	Facility or Area?	Submitted Inventory	Line was Installed	was Installed	Identification	Pigtail	Line Material	Material	Line	downstream of Lead?	Service Line	this Location?	Replaced	Replacement	property?	customer refused access to property
				_													
				_													
				_													
		_						-									

Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was	Year Customer Side Service Line	Source of Information Used for Service Identification	ine Gooseneck/	PWS-Owned Service Line Material	Customer Side Service Line	Classification for Entire Serivice	Was Galvanized Service Line Material ever		Previously Replaced at	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.	raciity of Area:	Submitted Inventory	Installed	was Installed	identification	rigian	Line Waterial	Material	Line	downstream of Lead?	Service Line	this Location?	перисси	перисетет	property?	to property
														<u> </u>	<u> </u>		

Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was	Year Customer Side Service Line	Source of Information Used for Service Identification	ine Gooseneck/	PWS-Owned Service Line Material	Customer Side Service Line	Classification for Entire Serivice	Was Galvanized Service Line Material ever		Previously Replaced at	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.	raciity of Area:	Submitted Inventory	Installed	was Installed	identification	rigian	Line Waterial	Material	Line	downstream of Lead?	Service Line	this Location?	перисси	перисетет	property?	to property
														<u> </u>	<u> </u>		

Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was	Year Customer Side Service Line	Source of Information Used for Service Identification	ine Gooseneck/	PWS-Owned Service Line Material	Customer Side Service Line	Classification for Entire Serivice	Was Galvanized Service Line Material ever		Previously Replaced at	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.	racinty of Area:	Submitted Inventory	Installed	was Installed	identification	rigian	Line Waterial	Material	Line	downstream of Lead?	Service Line	this Location?	перисси	перисетет	property?	to property
														<u> </u>	<u> </u>		

Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was	Year Customer Side Service Line	Source of Information Used for Service Identification	ine Gooseneck/	PWS-Owned Service Line Material	Customer Side Service Line	Classification for Entire Serivice	Was Galvanized Service Line Material ever		Previously Replaced at	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.	racinty of Area:	Submitted Inventory	Installed	was Installed	identification	rigian	Line Waterial	Material	Line	downstream of Lead?	Service Line	this Location?	перисси	перисетет	property?	to property
														<u> </u>	<u> </u>		

Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was	Year Customer Side Service Line	Source of Information Used for Service Identification	ine Gooseneck/	PWS-Owned Service Line Material	Customer Side Service Line	Classification for Entire Serivice	Was Galvanized Service Line Material ever		Previously Replaced at	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.	racinty of Area:	Submitted Inventory	Installed	was Installed	identification	rigian	Line Waterial	Material	Line	downstream of Lead?	Service Line	this Location?	перисси	перисетет	property?	to property
														<u> </u>	<u> </u>		

Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was	Year Customer Side Service Line	Source of Information Used for Service Identification	ine Gooseneck/	PWS-Owned Service Line Material	Customer Side Service Line	Classification for Entire Serivice	Was Galvanized Service Line Material ever		Previously Replaced at	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.	raciity of Area:	Submitted Inventory	Installed	was Installed	identification	rigian	Line Waterial	Material	Line	downstream of Lead?	Service Line	this Location?	перисси	перисетет	property?	to property
														<u> </u>	<u> </u>		

Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was	Year Customer Side Service Line	Source of Information Used for Service Identification	ine Gooseneck/	PWS-Owned Service Line Material	Customer Side Service Line	Classification for Entire Serivice	Was Galvanized Service Line Material ever		Previously Replaced at	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.	raciity of Area:	Submitted Inventory	Installed	was Installed	identification	rigian	Line Waterial	Material	Line	downstream of Lead?	Service Line	this Location?	перисси	перисетет	property?	to property
														<u> </u>	<u> </u>		

Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was	Year Customer Side Service Line	Source of Information Used for Service Identification	ine Gooseneck/	PWS-Owned Service Line Material	Customer Side Service Line	Classification for Entire Serivice	Was Galvanized Service Line Material ever		Previously Replaced at	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.	racinty of Area:	Submitted Inventory	Installed	was Installed	identification	rigian	Line Waterial	Material	Line	downstream of Lead?	Service Line	this Location?	перисси	перисетет	property?	to property
														<u> </u>	<u> </u>		

Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was	Year Customer Side Service Line	Source of Information Used for Service Identification	ine Gooseneck/	PWS-Owned Service Line Material	Customer Side Service Line	Classification for Entire Serivice	Was Galvanized Service Line Material ever		Previously Replaced at	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.	racinty of Area:	Submitted Inventory	Installed	was Installed	identification	rigian	Line Waterial	Material	Line	downstream of Lead?	Service Line	this Location?	перисси	перисетет	property?	to property
														<u> </u>	<u> </u>		

Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was	Year Customer Side Service Line	Source of Information Used for Service Identification	ine Gooseneck/	PWS-Owned Service Line Material	Customer Side Service Line	Classification for Entire Serivice	Was Galvanized Service Line Material ever		Previously Replaced at	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.	racinty of Area:	Submitted Inventory	Installed	was Installed	identification	rigian	Line Waterial	Material	Line	downstream of Lead?	Service Line	this Location?	перисси	перисетет	property?	to property
														<u> </u>	<u> </u>		

Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was	Year Customer Side Service Line	Source of Information Used for Service Identification	ine Gooseneck/	PWS-Owned Service Line Material	Customer Side Service Line	Classification for Entire Serivice	Was Galvanized Service Line Material ever		Previously Replaced at	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.	racinty of Area:	Submitted Inventory	Installed	was Installed	identification	rigian	Line Waterial	Material	Line	downstream of Lead?	Service Line	this Location?	перисси	перисетет	property?	to property
														<u> </u>	<u> </u>		

Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was	Year Customer Side Service Line	Source of Information Used for Service Identification	ine Gooseneck/	PWS-Owned Service Line Material	Customer Side Service Line	Classification for Entire Serivice	Was Galvanized Service Line Material ever		Previously Replaced at	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.	racinty of Area:	Submitted Inventory	Installed	was Installed	identification	rigian	Line Waterial	Material	Line	downstream of Lead?	Service Line	this Location?	перисси	перисетет	property?	to property
														<u> </u>	<u> </u>		

Service Address	Lead and Copper Sample site	Is this a high-risk	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was	Year Customer Side Service Line	Source of Information Used for Service Identification	ine Gooseneck/	PWS-Owned Service Line Material	Customer Side Service Line	Classification for Entire Serivice	Was Galvanized Service Line Material ever		Previously Replaced at	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the	Date of customer waiver or IDPH notification, if customer refused access
	number.	raciity of Area:	Submitted Inventory	Installed	was Installed	identification	rigian	Line Waterial	Material	Line	downstream of Lead?	Service Line	this Location?	перисси	перисетет	property?	to property
														<u> </u>	<u> </u>		

Marke Mark		Is this a high-risk	Service Line Newly	Year PWS- Owned Service		Source of Information Used for Service Line	Gooseneck/	PWS-Owned Service				Material of Service Line	Date of customer waiver
	Service Address	Facility or Area?	Identified Since Last Submitted Inventory	Line was	Side Service Line								customer refused access
				mstaneu									